

officals?

General Motors

General Motors LLC Compliance & Certification MC 483-331-500 Milford Proving Ground 3300 General Motors Road Milford, Michigan 48380-3726

March 22, 2011

MH-MW410

Mr. Gregory Orehowsky
Engine Programs Group
Certification & Compliance Division
U.S. Environmental Protection Agency
Mail Code 6403J
1200 Pennsylvania Avenue, NW
Washington, DC 20460

Emission Defect Information Report

2010 / 2011 6.6L Diesel Engines Equipped with Select Catalyst Reduction Systems
Diesel Exhaust Fluid Injection System

General Motors submits the attached Emission Defect Information Report in accordance with the requirements of 40 CFR Part 85, Subpart T, Section 85.1903.

Questions should be addressed to Mr. Chris Brown at (248) 255-7398.

Sincerely

David P. Garrett, Director Compliance & Certification

DPG/CSB Attachments

EMISSION DEFECT INFORMATION REPORT FOR U.S. ENVIRONMENTAL PROTECTION AGENCY

Information Required by 40 CFR Part 85, Subpart T, Section 85.1903

MW410

Problem Description –	Select	One	Only
-----------------------	--------	-----	------

	_X_Defect	ive/Incorr	ect Ca	atalyst Compone	nt/System	
	Defect	ive/Incorr	ect Co	mputer Related	(Other than C	BD)
	Defec	tive/Incor	rect Cr	rankcase Ventila	ition Compone	ent/Śystem
	Defec	tive/Incor	rect E0	GR System		•
	Defec	tive/Incor	rect El	ectrical Mechan	ical & Cooling	Systems
				vaporative Emiss		
				khaust System		
				tel Delivery Con	ponent	
				ıel Tank Compo	•	
				ybrid Vehicle Co		em
				, nition Compone		
				take Manifold		
	Defect	ive/Incon	ect Mo	onitoring/Measu	rina Sensor/S	vstem
				BD System	•	* *
				xygen Sensor		* ***
				ECI Label	•	
						er'
California only	? Yes		No	X		
						
Mil illumination	? Yes	<u>X</u>	No			

Description of the defect.

Certain 2010 and 2011 Chevrolet Express/ Silverado and GMC Savanna/ Sierra vehicles equipped with 6.6 liter diesel engines and Select Catalyst Reduction (SCR) systems have been built with the following Diesel Exhaust Fluid (DEF) injection system anomalies:



- Certain DEF system warnings and speed limiting inducement sequences could be temporarily interrupted before servicing of the DEF system.
- Under sustained cold weather conditions below the freeze temperature of DEF, the
 injected DEF quantity could deplete the amount of thawed liquid DEF causing a loss of
 DEF injection pressure resulting in DEF system malfunction warnings and vehicle speed
 limiting inducements.
- Under sustained cold weather conditions below the freeze temperature of DEF and after certain driving maneuvers, the DEF system could fail to recognize a DEF system fluid refill resulting in eventual DEF system low fluid level warnings and vehicle speed limiting inducements.
- After certain driving maneuvers and/or sustained cold weather conditions below the freeze temperature of DEF, DEF injection quantity could be temporarily reduced from the intended injection amount.

Emissions impact.

The impact of these concerns on emission has not been measured. Reduced DEF exhaust stream injection could result in reduced NOx emissions control.

Driveability problems.

When the vehicle speed limiting inducement strategy is initialized as the result of these concerns, vehicle operators will notice a progressive vehicle speed limitation sequence that could ultimately prevent the vehicle from being driven greater than 4 miles per hour.

How Was Defect Determined

The defect was determined in accordance with applicable legal requirements.

Available Emissions Data.

There has been no emission data collected in connection with the concerns identified in this report.

Addresses of the plant(s) at which the potential defective vehicles or engines were produced.

General Motors
Fort Wayne Assembly
12200 Lafayette Ctr. Road
Fort Wayne, IN 46783

General Motors Flint Assembly G-3100 Van Slyke Road Flint, MI 48551

General Motors
Wentzville Assembly
P.O. Box 716
Wentzville, MO 63385

Anticipated manufacturer follow-up.

Modified Engine Control Module (ECM) software and calibrations that address the concerns identified in this report are currently under development. GM anticipates that the modified software and calibrations will be installed into the 2011 model year production vehicles and released for service reprogramming when finalized. Further, General Motors will consider the need to conduct a Voluntary Emission Recall to reprogram the ECM in the vehicles identified in this report when the improved software and calibrations become available.

Notes

General Motors LLC does not, by filing this report, admit the existence of a defect subject to the Production and Performance Warranties provided by Section 207(a) and 207(b) of the Clean Air Act, as amended, or Section 43204 of the California Health and Safety Code.

MW410 Estimated Number of Vehicles Affected

Total Model Year

2010 = 1721 2011 = 71486

Model	Engine	Emission	Vehicle	Model	
<u>Year</u>	<u>Family</u>	Standard	Make	Name	Total
2010	BGMXH06.6590	50-State	Chevrolet	Express	1637
annaganga <u>sa da dalaman nagang nganan akaban na naga 1977 (di 1980)</u> kaba		50-State	GMÇ	Savana	84
2011	BGMXH06.6590	50-State	Chevrolet	Express	1632
		50-State	Chevrolet	Silverado	5391
		50-State	GMC	Savana	428
		50-State	GMC	Sierra	1519
2011	BGMXD06.6365	50-State	Chevrolet	Silverado	12792
		50-State	GMC	Sierra	4854
2011	BGMXD06.6355	50-State	Chevrolet	Silverado	29715
		50-State	GMC	Sierra	15155

These volume estimates were generated from General Motors corporate data files that identify produced and sold vehicles by build options and emissions package sales options.